Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	240	562/545.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L2	212	562/547.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L3	414	L1 or L2	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L4	2549842	gas	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L5	884969	monitor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L6	38905	L4 same L5	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L7	6230277	control	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L8	353839	L7 same L4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L9	2362653	automat\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L10	26179	L8 same L9	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L11	100242	L9 adj L7	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41

L12	2603	L11 near10 L4	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L13	0	L3 and L12	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L14	0	L3 and L11	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L15	335693	raw adj material	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L16	437606	feedback	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L17	0	L3 and L16	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L18	386946	reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L19	7846	L16 and L18	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L20	2083	L16 same L18	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR ·	ON	2006/04/18 09:41
L21	43042	("562").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2006/04/18 09:41
L22	568828	oxidation	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L23	337	L20 and L22	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41

			· · · · · · · · · · · · · · · ·			
L24	1	L3 and L10	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L25	2	"4472527".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L26	2	"4520127".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L27	2	"2001114706"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:53
L28	26	"114706"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR.	ON	2006/04/18 09:41
L29	4	L3 and L6	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L30	84	L3 and L8	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L31	6	L30 and L9	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L32	11	"1080780"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L33	. 39	"122805"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L34	23	"120984"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41
L35	46	L20 same L22	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:41

			,	г	r	
L36	3279	(Stop\$ and (flow adj rate)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:51
L37	2	I21 and I36	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON .	2006/04/18 09:49
L38	0	(Stop\$ and (flow adj rate) and oxidat?).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:18
L39	26	"114706"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 09:53
L40	0	(Stop\$ and (flow adj rate) and oxidat? and (gas near2 phase)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:19
L41	0	(Stop\$ and (flow adj rate) and oxidat? and (gas near10 phase)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:19
L42		(Stop\$ and (flow adj rate) and oxidat? and (gas adj phase)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:19
L43	0	((Stop\$ or terminat?) and (flow adj rate) and oxidat? and (gas adj phase)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:20
L44	5	((Stop\$ or terminat?) and (flow adj rate) and oxidat? and (gas adj phase))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2006/04/18 10:20